




MOTOR COACH
INDUSTRIES

Going further!



23522994CG

23530249CG

23518219CG

Order pulleys based on the specifications below:

Part Number	Description – application
23522994CG	12 groove for Bosch alternator
23530249CG	10 groove for Bosch alternator with EGR engine
23518219CG	12 groove, 4" O.D., 50 DN

*New to MCI's
Coach Guard® line of products*

Dependable, value-priced Coach Guard alternator drive pulleys help keep your fleet pulling ahead

Hard-working coaches deserve hard-working parts. MCI's new, high-quality Coach Guard alternator drive pulleys get the job done, and at a fraction of the cost of OE replacement pulleys. Please mark your records to show MCI as your supplier for this product.

Coach Guard alternator drive pulleys will provide optimum reliability and value for the coaches in your fleet. These pulleys are:

- Manufactured to meet or exceed OE specifications.
- Machined from solid rolled steel—not cast—no balancing required.
- Zinc dichromate finish deters corrosion and extends service life.

MCI PRO SUPPORT.

STANDING BESIDE YOU. ALL THE WAY.

Parts, service, training and more
to keep you going further!

In the U.S.

MCI Fleet Support
MCI Service Parts, Inc.
1700 E. Golf Road
Schaumburg, IL 60173
Toll Free (800) 323-1290
Toll Free Fax (800) 525-4569

In Canada

MCI Fleet Support
Motor Coach Industries Limited
260 Toronto Street
Newcastle, ON L1B 1C2
Toll Free *English* (800) 665-0155 *Français* (800) 546-3457
Toll Free Fax (800) 872-2486

Printed on recycled paper products